



FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

1. Name of the Officer : Sunesh Kumar P.S.
2. Name of School : DAWN international School, Puthencruz.
3. Location with name of Education District/Sub District : Aluva / Kolenchery.
4. Classification of buildings as specified in col 4 of the application for fitness certificate : Basement Floor - 33.95 x 34.68 x 3.60 m
Ground Floor - 33.24 x 34.68 x 3.60 m
First Floor - 33.24 x 34.68 x 3.60 m
Second Floor - 33.24 x 6.0 x 3.60 m
Class rooms - 7 Nos - 6 x 6 x 3.6
LAB, - 18.6 x 6 x 3.6
5. Period for which the certificate is issued : 2020-2021 Third Floor - 16.68 x 6 x 3.6
Class rooms - 8 Nos - 6 x 6 x 3.6
Entertainment room - 12.36 x 6 x 3.6 m
6. Nature of defect, if any : Nil
7. a) Foundation and basement : RCC Footing
b) Superstructure : RCC framed Structure
c) Doors and windows : Country Wood
d) Wood work wrought and put up : Country wood
e) Roof : RCC slab
f) Flooring : Ceramic flooring.
8. any major defects noticed which will render the building unsafe in any manner : No
9. whether maintenance works have been done properly : Yes
10. whether the structure is sound or not for conducting classes : Yes

Certified that the school was inspected by me on 07/01/2021 and found to be fit to conduct classes for the period 2020-2021 under normal weather conditions (academic year)

Place: Puthencruz.
Date: 07/01/2021



[Signature]
ASSISTANT ENGINEER
PSGD SECTION
ADAVUCODE-PUTHENCRUZE

PRINCIPAL
DAWN INTERNATIONAL SCHOOL
VELLOORKARA P.O., KOCHI - 682 300

[Signature]

For DAWN INTERNATIONAL SCHOOL